Operator: AMEREN ILLINOIS COMPANY Operator ID:	
Inspection Date(s): 11/10/2015, 11/12/2015, 11/13/2015 Man Days	
Inspection Unit: Jacksonville	
Location of Audit: Jacksonville	
Exit Meeting Contact: Chris Juliusson	
Inspection Type: Standard Inspection - Record Audit	
Pipeline Safety Representative(s): Jim Watts, Bryan Pemble	
Company Representative to Receive Report: Michael Fuller	
Company Representative's Email Address: mfuller2@ameren.com	

Headquarters Address Information:	300 Liberty	
	Peoria, IL 61602	
	Emergency Phone#: (800) 755-5000	
	Fax#:	
Official or Mayor's Name:	Ron Pate	
	Phone#: (217) 424-6518	
	Email:	
Inspection Contact(s)	Title	Phone No.
John Bozarth	Manager Gas Compliance and Training	(217) 625-6854
Chris Juliusson	Quality Assurance Consultant	

Gas System Operations	Status
Gas Transporter	Panhandle Eastern and ANR
Annual Report (Form 7100.1-1) reviewed for the year:	Not Checked
General Comment:	
The Annual DOT Report review is conducted at the Ameren Illinois Training Center in Pawnee, Illinois. This was not reviewed during this	s audit.
Unaccounted for Gas	Not Checked
General Comment:	
Unaccounted for Gas is reviewed during the Annual DOT Report review conducted at the Ameren Illinois Training Center in Pawnee, Illin	ois.

General Comment:		
This is reviewed during the annual report review cord 2014.	nducted at the Ameren Illinois Training Center located in Pawnee, Illinois. This was	s last reviewed in February
Miles of Main		Not Checked
General Comment:		•
This is reviewed during the annual report review con 2014.	nducted at the Ameren Illinois Training Center located in Pawnee, Illinois. This was	s last reviewed in February
Is the operator maintaining documentation (MAOP)	n verifying their Maximum Allowable Operating Pressure(s)?	Satisfactory
General Comment:		
System MAOP's are recorded in the Pressure Regul Illinois.	lating section of GCS and the MAOP records are retained by the engineering depa	nrtments within Ameren
Operating Pressure (Feeder)		250
Operating Pressure (Town)		0.4, 5, 8.5, 20,25, 35, 42,45, 50
Operating Pressure (Other)		Not Applicable
General Comment:		1
There are no other types of systems.		
MAOP (Feeder)		300
MAOP (Town)		1, 10, 55, 60
MAOP (Other)		Not Applicable
General Comment:		•
There are no other types of systems.		
Does the operator have any transmission	pipelines?	No
General Comment:		-
There is no transmission piping in the Jacksonville S	Service Area.	
Regu	latory Reporting Records	Status
[191.5]	Were Telephonic Notices of Incidents reported to the NRC (800-424-8802)?	Not Applicable
General Comment:	•	•
There were no reportable incidents in the Jacksonvii	lle Service Area in 2013-2014.	
[191.9(a)]	Was a DOT Incident Report Form F7100.1 submitted within 30 days after detection of an incident?	Not Applicable
General Comment:		•

There were no reportable incidents in the Jacksonville	Service Area in 2013-2014.	
[191.9(b)]	Were any supplemental incident reports submitted when deemed necessary?	Not Applicable
General Comment:		
Due to no reportable incidents occurring no supplemen	tal reports were required.	
Did the operator have any plastic pipe failure	es in the past calendar year?	Yes
General Comment:		
There was an issue with pinholes in a 1/2 inch plastic p The piping was then sent to GTI for further analysis.	e service line piping identified in 2015. This was sent to their gas materials specia	list for further review.
Did the operator take action to mitigate safet components?	ty concerns relating to the failure of the PE or pipeline	Yes
General Comment:		
	that required reporting. In March of 2015 a section of Aldyl A service line was repilure Department at Ameren for further review. The piping was sent to GTI for furth	
[191.23(a)]	Did the operator report Safety Related Conditions?	Not Applicable
General Comment:		
There were no Safety Related Conditions to report in 2	013-2014.	
[191.25]	Did the Operator file a Safety Related Condition Report within 5 working days of determination, but not later than 10 working days after discovery?	Not Applicable
General Comment:	,	
There were no Safety Related Conditions to report in 20	013-2014.	
[192.16(c)]	Customer Notification: Has the operator notified each new customer within 90 days about the customer's responsibility regarding buried piping, however, operators of a master meter may continuously post a general notice in a permanent location?	Satisfactory
General Comment:		
This requirement is met by a customer notification that service.	includes a Natural Gas Safety Flyer that is sent to a new customer within 90 days	of signing up for gas
TES	ST REQUIREMENTS	Status
[192.517(a)][192.505,192.507,192.511(c)]	Are pressure test records being maintained for piping operating above 100 psig?	Satisfactory
General Comment:		
Staff reviewed the pressure test performed at a farm tagwas operating above 100 psig. Test was performed an	p at 6 Naples Lane in Naples where piping was replaced on the high side due to ex d documented as required.	xternal corrosion and
[192.517(b)][192.511,192.509,192.513]	Are pressure test records being maintained for at least 5	Satisfactory

	years on piping operating below 100 psig?	
General Comment:	<u> </u>	•
Pressure test records are maintained for the life	of the system.	
[192.603(b)][192.725]	Were service lines temporarily disconnected from the main properly tested prior to reconnection?	Satisfactory
General Comment:		
A review of services in 2013-2014 where they we service and were properly documented.	ere temporarily disconnected from their supply determined they were tested as required by	pefore restoring gas
	UPRATING	Status
Category Comment:		
No uprating was performed in the Jacksonville S	System in 2013-2014.	
[192.555][192.555]	Has the operator maintained documentation of uprating activities when uprating a pipe to a pressure that will produce a hoop stress of 30% or more SMYS?	Not Applicable
[192.557][192.557]	Has the operator maintained documentation of uprating activities when uprating a pipe to a pressure that will produce a hoop stress of less than 30% SMYS?	Not Applicable
OPERATIONS		Status
[192.603(b)][192.605(a)]	Has the operator conducted a review of the Operations and Maintenance Manual once per yr/15 months?	Not Checked
General Comment:		
This is reviewed during the Pawnee Training Ce Pawnee Training Center in 2014.	enter Audit and was not reviewed as part of this audit. This was last reviewed during the a	audit conducted at the
Has the operator conducted a review of	of the Operator Qualification Plan once per yr/15 months?	Not Checked
General Comment:		
This is reviewed during the Ameren Training Ce	nter Audit and was not reviewed as part of the Jacksonville audit.	
[192.603(b)][192.605(b)(3)]	Are construction records, maps, and operating history available to operating personnel?	Satisfactory
General Comment:	<u> </u>	•
Maps are available through portable data termir local operating centers. Staff reviewed the as b	als and operating history is available through their headquarters office. As built drawings uilt drawings or the Bartlett Grain installation.	are also retained in the
192.603(b)][192.605(b)(8)]	Has the operator periodically reviewed personnel's work to determine the effectiveness of normal O&M procedures when deficiencies are found?	Satisfactory
General Comment:	•	•
Ameren utilizes both Supervisors and Quality Astronomy Job Behavior Observation (JBO) forms	ssurance Personnel to review work performed by company personnel. These reviews are sompleted by the Local Supervisor.	e documented. Staff

CONTIN	UING SURVEILLANCE RECORDS	Status
[192.603(b)][192.613(a)]	Has the operator reviewed continuing surveillance records for class location changes, failures, leak history, corrosion, changes in cathodic protection, and other unusual operating and maintenance conditions?	Satisfactory
General Comment:		
patrols performed by the Jacksonville Service A.	nsmission Department at the Decatur Plaza and are reviewed during the transmission rec rea personnel indicate there is only one patrol on an exposed segment of main. This was ce annually in 2013-2014. There were no changes in class location determined during col during continuing surveillance.	the only critical main
[192.491][192.489]	Does the operator have records verifying if exposed cast iron was examined for evidence of graphitization and if necessary what appropriate action was taken concerning graphitization?	Not Applicable
General Comment:		
There is no cast iron in the Jacksonville Service	Area.	
[192.603(b)][192.755]	Does the operator have surveillance records of cast iron pipelines, including appropriate action resulting from tracking circumferential cracking failures, study of leak history, or any other unusual operating and maintenance conditions?	Not Applicable
General Comment:	·	
There is no cast iron in the Jacksonville Service	Area.	
[192.603(b)][192.753(a)]	Is each cast iron caulked bell and spigot joint that is subject to a pressure of more than 25 (psig.) sealed as required?	Not Applicable
General Comment:	·	
There is no cast iron in the Jacksonville Service	Area.	
[192.603(b)][192.753(b)]	Is each cast iron caulked bell and spigot joint that is subject to a pressure of 25 (psig.) or less and is exposed for any reason sealed as required?	Not Applicable
General Comment:		
There is no cast iron in the Jacksonville Service	Area.	
DAM	AGE PREVENTION RECORDS	Status
Category Comment:		
The Damage prevention records are reviewed d last reviewed in February 2014.	luring a separate audit of the Ameren Damage Prevention Department performed in Pawn	ee, Illinois. They were
[192.603(b)][191.11(a)]	Did the operator track the number of damages per 1000 locate requests for the previous years?	Not Checked

Has the number of damages increased	or decreased from prior year?	Not Checked
[192.603(b)][192.617]	Does the operator track records of accidents due to excavation damage to ensure causes of failures are addressed to minimize the recurrence?	Not Checked
[192.603(b)][192.614(c)(3)]	Does the operator provide documentation pertaining to notification of excavation, marking, positive response, and the availability and use of the one call system?	Not Checked
Does the operator have a Quality Assu facilities?	rance Program in place for monitoring the locating and marking of	Not Checked
Do pipeline operators include performa	nce measures in facility locating contracts?	Not Checked
[IL ADM. CO.265.100(b)(1)]	Was third party damage to mains involving a release of gas reported to ICC JULIE Enforcement? http://www.icc.illinois.gov/julie/	Not Checked
Has the Operator adopted applicable s	ections of the Common Ground Alliance Best Practices?	Not Checked
Were Common Ground Alliance Best F	Practices discussed with the Operator?	Not Checked
	EMERGENCY PLANS	Status
[192.603(b)][192.615(b)(1)]	Are supervisors, responsible for emergency action, furnished copies of the latest edition of the Emergency Plan?	Satisfactory
General Comment:	·	•
The Emergency plan is available to all personne annually. The Jacksonville Service Area reviews	via mobile terminals and they are provided copies of the current edition of the plan that were completed in January 2013 and January of 2014.	t is reviewed as a group
[192.603(b)][192.615(b)(2)]	Has the operator maintained documentation that the appropriate operating personnel have received training to assure they are knowledgeable of emergency procedures and that the training was effective?	
General Comment:	•	•
Staff reviewed the rosters for January 2013-2014	for the Emergency Plan Reviews and determined all Jacksonville personnel attended	the required training.
[192.603(b)][192.615(b)(3)]	Has the operator maintained documentation of employee activity reviews to determine whether the procedures were effectively followed in each emergency?	Not Applicable
General Comment:	•	-
No emergencies occurred in the Jacksonville Se	rvice Area that required a review to be completed.	
[192.603(b)][192.615(c)]	Has the operator maintained documentation that the operator established and maintained liaison with appropriate fire, police and other public officials?	Not Checked
General Comment:	·	

[192.603(b)][192.615(a)(3)]	Did the review of emergency response time intervals regarding odor/leak complaint documentation indicate adequate emergency response intervals were achieved?	Satisfactory
General Comment:	<u> </u>	
Review of annual spreadsheets for leak calls indica	te there were no leak calls that exceeded 60 minutes in 2013-2014 in Division II.	
O	DORIZATION OF GAS	Status
[192.603(b)][192.625(f)]	Has the operator maintained documentation of odorant concentration level testing using an instrument?	Satisfactory
General Comment:	<u> </u>	
Review of odorant testing indicates the monthly test	ts were conducted as required and levels were readily detectable below 1/5 the lower of	explosive limit.
[192.603(b)][192.625(e)]	Has the operator maintained documentation of odorizer tank levels?	Unsatisfactory
Issue Comment:	·	
odorometer tests did not indicate high levels of odor issues that Staff has is the odorometer tests utilized was detected. Due to this, Staff is unable to determ corrective action that should be taken when high od of odorant usage are detected to determine if over a Ameren provided Staff with a revised O&M procedu currently an active procedure. The revised procedu	ew Staff observed levels being calculated up to 5 lbs/MMCF on these bypass odorizers rization and there were no indications of increases in leak reports being received from it to determine if over odorization was present were not performed at the time the high I nine if over odorization was actually taking place at the time it was detected. Staff suggestorization levels are detected, should include an odorometer survey to be performed at adorization is actually occurring or it is an issue with the level measurement device on the for odorization that will be released in January of 2016. This revision addresses this are requires initiation of an odorometer survey, making changes to the odorizer setting, fixer to view usage and possible detect intermittent issues using more frequent inspections.	their customers. The levels of odorant usage gests as part of the the time the high levels the bypass odorizer. Is issue but is not flaring over odorized
[192.603(b)][192.625(f)(1)]	Are master meter operators receiving written verification of odorant concentration levels from their gas supplier?	Not Applicable
General Comment:		
This requirement does not apply to this operator.		
[192.603(b)][192.625(f)(2)]	Has the master meter operator maintained documentation of sniff tests performed as required by this section?	Not Applicable
[192.603(b)][192.625(f)(2)]  General Comment:	documentation of sniff tests performed as required by this	Not Applicable
	documentation of sniff tests performed as required by this	Not Applicable
General Comment:  This requirement does not apply to this operator.	documentation of sniff tests performed as required by this	Not Applicable Status
General Comment:  This requirement does not apply to this operator.	documentation of sniff tests performed as required by this section?	
General Comment:  This requirement does not apply to this operator.  PATRO	documentation of sniff tests performed as required by this section?  LLING & LEAKAGE SURVEY  Is the operator patrolling business districts at a minimum	Status
General Comment: This requirement does not apply to this operator.  PATRO  [192.603(b)][192.721(b)(1)]	documentation of sniff tests performed as required by this section?  LLING & LEAKAGE SURVEY  Is the operator patrolling business districts at a minimum of 4 per year/4 1/2 months?	Status

General Comment:		
There is one segment of main in Jacksonville that is exposed	and was inspected twice annually in 2013-2014.	
[192.603(b)][192.723(b)(1)]	Is the operator performing leakage surveys in business districts at a minimum of 1 per year/ 15 months? If the operator has inside meter sets that meet this criterion then were those surveyed?	Unsatisfactory
NOPV Comment:		
indicated and surveyed in 2013 that were not included on the The first location was at Chambers Street and S. Diamond ar	in 2014 for Jacksonville, Illinois, there were two segments of main and service 2014 maps utilized to conduct the business district leak surveys thus were a not the second was a segment of main and one service line on Stevenson Dr by were included and leak surveyed during the 2015 Business District Survey	not surveyed in 2014. ive North of Morton
[192.603(b)][192.723(b)(2)]	Is the operator performing leakage surveys outside a business district at a minimum of every 5 years/63 months? Is the operator performing leakage surveys on cathodically unprotected pipelines at a minimum of every 3 years/39 months? If the operator has inside meter sets that meet this criterion then were those surveyed? If the operator has yard lines then are those being surveyed?	Satisfactory
General Comment:	•	
Review of distribution leak surveys conducted outside of the 5 years/63 months.	business districts in 2013-2014 indicates the surveys were completed within	the required intervals of
YARD LIN	ES - RESIDENTIAL	Status
[220 ILCS 2.2.03]	Has the operator designated and documented the location of all services where the meter is located more than 3 feet away from the wall of a residence?	Satisfactory
General Comment:	-	
Yard lines were surveyed on a three year interval in the Jack intervals.	sonville Service Area. The surveys conducted in 2013 and 2014 were comp	leted within the required
[192.463,220 ILCS 2.2.03][220 ILCS 2.2.03]	Has the operator determined if cathodic protection is required on these services?	Not Applicable
General Comment:	•	
All yard lines are considered as unprotected and are surveye	d on a three year interval.	
[192.723(b)(1),192.723(b)(2)][220 ILCS 2.2.03]	After the determination of the cathodic protection requirements, has the operator surveyed each line within the required leakage survey intervals?	Satisfactory
General Comment:	•	
All yard line surveys were completed as required in 2013-201	4.	
ABANDONMENT or DEACTIV	ATION of FACILITIES PROCEDURES	Status
[192.603(b)][192.727(b)]	Did the operator maintain documentation demonstrating that each pipeline abandoned in place was disconnected	Satisfactory

	year/15 months?	
[192.603(b)][192.743(a)]	Is the operator inspecting pressure limiting and regulating stations for adequate capacity at a minimum of 1 per	Satisfactory
2013-2014, indicate the inspections were complete	ion documentation maintained in the Gas Compliance System (GCS) for the Jacksonviled as required by this section.	le Service Area for
[192.603(b)][192.739(a)]	Is the operator inspecting and testing the pressure limiting and regulating stations at a minimum of 1 per year/15 months?	Satisfactory
	RE LIMITING AND REGULATION	Status
No piping was abandoned that crossed a navigabl	e water way in 2013-2014 in the Jacksonville Service Area.	
General Comment:		
[192.727(g)][192.727(g)]	Did the operator maintain documentation for each abandoned onshore pipeline facility that crosses over, under or through a commercially navigable waterway?	Not Applicable
General Comment:  Review of new main installation documentation incombustible mixture.	licates the newly installed piping was purged of air using gas in a manner that prevente	d achieving a
[192.603(b)][192.727(e)]	Did the operator maintain documentation when air was used for purging that a combustible mixture was not present after purging?	Satisfactory
Review of leak customer complaint documentation meter was removed the outlets are plugged.	indicates that when service to a customer was disconnected the valve is locked in the	closed position. If the
General Comment:	and open pipe ends search.	
[192.603(b)][192.727(d)]	Did the operator maintain documentation demonstrating that whenever service to a customer was discontinued access to gas was either; locked, prevented by a mechanical fitting, or disconnected from the gas supply and open pipe ends sealed?	Satisfactory
prevent migration.	2013-2014 indicates that piping not being maintained was disconnected, purged of gas	and was sealed to
General Comment:		
[192.603(b)][192.727(c)]	Did the operator maintain documentation demonstrating that each inactive pipeline that is not being maintained under this part was disconnected from all sources and supplies of gas; purged of gas?	Satisfactory
Review of service line and main abandonment doo	rumentation indicate they were abandoned as required in 2013-2014.	
General Comment:		
Compared Company and		

Review of the pressure regulating station capacity revieus Jacksonville Service Area and the capacities were indicated in the capaci	ews maintained in GCS indicates the calculations were completed as required in 20 cated being adequate.	013-2014 for the
[192.603(b)][192.743(b)]	If the operator used calculations to determine sufficient capacity, were the calculation reviews documented at a minimum of 1 per year/15 months?	Satisfactory
General Comment:		
Review of the pressure regulating station capacity review Jacksonville Service Area.	ews maintained in GCS indicates the calculations were completed as required in 20	013-2014 for the
[192.603(b)][192.741(a),192.741(b)]	Is each distribution system supplied by more than one district pressure regulating station, or where required by the operator on a system supplied by a single regulating station, equipped with telemetering or recording pressure gauges to indicate the gas pressure in the district?	Not Checked
General Comment:		
	ore than one feed or supply are monitored using electronic pressure recorders. The ed, Gas Control dispatches the local personnel to take corrective actions. This doc dit.	
[192.603(b)][192.741(c)]	If there were indications of abnormally high- or low- pressure, were actions taken to correct any unsatisfactory operating conditions?	Not Checked
General Comment:		
Review of corrective actions is performed during the G	as Control audit and was not checked during the Jacksonville Service Area audit.	
[192.603(b)][192.743(a),192.743(b),192.195	(b)(2)] Is overpressure protection provided by the supplier pipeline downstream of the take point?	No
General Comment:		
overpressure protection. Ameren is either taking over	ure protection at locations within the Jacksonville Service Area where the supplier the responsibility for pressure regulation or installing a relief device in these instant insure operation, confirm set point and confirm capacity. These inspections were red they were completed as required.	ces. Where reliefs have
[192.603(b)][192.743(a)]	If Yes, does the operator have documentation to verify that these devices have adequate capacity?	Not Applicable
General Comment:	•	
There are no locations in the Jacksonville Service Area	where they rely on the supplier for overpressure protection.	
VAI	LVE MAINTENANCE	Status
[192.603(b)][192.747(a),192.747(b)]	Did the operator inspect and maintain distribution valves necessary for the safe operation of the system at a minimum of 1 per year/15 months?	Satisfactory
General Comment:		
Review of Emergency Valve inspections for 2013-2014	for the Jacksonville Service Area indicates they were inspected as required in 201	13-2014.
[192.603(b)][192.749(a)]	Did the operator inspect and maintain vaults > 200 cubic feet at a minimum of 1 per year/15 months?	Not Applicable

General Comment:		
There are no vaults meeting these requirements	in the Jacksonville Service Area.	
Investigation Of Failures		Status
[192.603(b)][192.617]	Did the operator experience accidents or failures requiring analysis?	Not Applicable
General Comment:		
No failures occurred in 2013-2014 that required	analysis.	
WELDING OF STEEL PIPE		Status
Category Comment:		
These records are maintained and reviewed dur	ring the Pawnee Training Center Audit which was last done in 2014.	
[192.603(b)][192.225(b)]	Does the operator have documentation for their qualified welding procedure?	Not Checked
[192.603(b)][192.227,192.229]	Does the operator have documentation of welder qualification as required?	Not Checked
[192.807]	Does the operator have documentation of welder OQ records?	Not Checked
[192.709][192.243(b)(2)]	Does the operator have documentation of NDT personnel qualification as required?	Not Checked
[192.709][192.243(f)]	Does the operator have documentation of NDT testing performed?	Not Checked
JOINING OF	MATERIAL OTHER THAN WELDING	Status
Category Comment:  These records are maintained and reviewed during the second	ring the Pawnee Training Center Audit which was last done in 2014.	
[192.603(b)][192.285]	Are persons making joints with plastic pipe qualified?	Not Checked
[192.603(b)][192.287]	Are persons inspecting plastic pipe joints qualified?	Not Checked
[192.603(b)][192.283]	Are qualified joining procedures for plastic pipe in place?	Not Checked
CORROSION CONTROL RECORDS		
[192.491(a)][192.491(a)]	Has the operator maintained maps or records of cathodically protected piping, cathodic protection facilities, galvanic anodes, and neighboring structures bonded to the cathodic protection system?	Satisfactory
General Comment:  The location of cathodically protected piping and viewed by field personnel at any time.	d the facilities associated with cathodic protection are recorded in their electronic mapping	system that can be
[192.491][192.459]	Has the operator maintained documentation of an	Satisfactory

	examination when buried pipe was exposed?	
General Comment:		
Review of buried piping inspections performed in 2013-2014	indicate inspections were performed when required and had the required fiel	ds completed.
[192.491][192.465(a)]	Has the operator maintained documentation of annual pipe-to-soil monitoring performed at a minimum of 1 per yr/15 months and/or isolated services or short sections of main less than 100 feet at a minimum of 10% annually?	Satisfactory
General Comment:		
Review of isolated main segments and isolated services man protected status in 2013-2014.	intained in GCS indicate they were inspected as required and were indicating	potentials indicating a
[192.491][192.465(b)]	Has the operator maintained documentation of rectifier or other impressed current power sources inspections at a minimum of 6 per year/ 2 1/2 months?	Satisfactory
General Comment:		
Review of rectifiers inspections performed in the Jacksonville	e Service Area indicate they were inspected as required in 2013-2014.	
[192.491][192.465(c)]	Has the operator maintained documentation of each critical interference bond, reverse current switch, diode, etc. inspections at a minimum of 6 per year/ 2 1/2 months and/or non-critical interference bond inspections at a minimum of 1 per year/15 months?	Satisfactory
General Comment:		
Review of critical bonds located in the Jacksonville Service A	Area indicate they were inspected as required in 2013-2014.	
[192.491][192.465(d)]	Has the operator taken prompt remedial actions to correct any deficiencies indicated by the monitoring?	Satisfactory
General Comment:		
Review of low potentials identified in the Jacksonville Service	e Area had corrective actions taken to correct the deficiencies identified in 20	13-2014.
[192.491][192.465(e)]	Has the operator maintained documentation of unprotected pipeline surveys, inspections, or tests at a minimum of 3 years/39 months?	Not Applicable
General Comment:		
There is no unprotected piping owned and operated by Ame	ren Illinois in the Jacksonville Area Systems.	
[192.491][192.467(a),192.467(c),192.467(d)]	Has the operator maintained documentation of inspections or tests for electrical isolation at casings?	Satisfactory
General Comment:		
Review of casing inspection testing conducted in 2013-2014	indicates electrical isolation is being maintained on the installations maintained	ed in GCS.
[192.491][192.469]	Does the operator have a sufficient number of test stations or other contact points for electrical measurement to determine the adequacy of cathodic	Satisfactory

	protection?	
General Comment:		
Review of the number of test points indicates a maintained in GCS up to November of 2014.	an adequate number of test points are present on piping in the Jacksonville Service Area. T	These points were
[192.491][192.471]	Has the operator maintained documentation of corrective actions taken when a test lead is no longer electrically conductive?	Not Applicable
General Comment:	·	
No issues were identified with test leads in 201	13-2014.	
[192.491][192.473(b)]	Has the operator maintained documentation of inspections or tests to assure their cathodic protection system is not affecting adjacent underground metallic structures?	Satisfactory
General Comment:	·	
	are they are not affecting neighboring facilities. If changes are made to the rectifier further engineering facilities. No changes were made to rectifiers settings that warranted evaluations in	
[192.491][192.475(a)]	Has the operator maintained documentation of investigations or steps taken to minimize internal corrosion due to transportation of corrosive gas?	Not Applicable
General Comment:		
Ameren does not transport corrosive gas in the	e piping located in Jacksonville Service Area.	
[192.491][192.475(b)]	Has the operator maintained documentation of internal surface inspections performed when pipe is removed for any reason?	Satisfactory
General Comment:		
Review of piping inspection documentation ind corrosion were identified.	licates they conducted internal corrosion inspection on piping removed in 2013-2014. No in	ndications of internal
[192.491][192.477]	Has the operator maintained documentation of internal corrosion coupon monitoring at a minimum of 2 per year/ 7 1/2 months?	Not Applicable
General Comment:	<u> </u>	
Ameren does not transport corrosive gas in the Service Area.	e piping located in Jacksonville Service Area. Due to this coupon testing is not conducted in	n the Jacksonville
[192.491][192.481]	Has the operator maintained documentation of atmospheric corrosion control monitoring at a minimum of 1 per 3 years/39 months?	Satisfactory
General Comment:		
	d in conjunction with the leak survey which is performed on a 4 year interval per their waive	r for Atmospheric
corrosion survey. There were no issues identified	fied where piping was replaced due to atmospheric corrosion in 2013-2014.	

[192.491][192.479]	Has the operator maintained documentation of corrective action where atmospheric corrosion was discovered?	Satisfactory
General Comment:	<u> </u>	
Review of documentation of corrective actions where area performed in 2013-2014, indicate these conditions were co	s of issues with atmospheric corrosion or coating disbondment were identified a prected as required.	luring the leak surveys
[192.491][192.483(a),192.483(b),192.483(c)]	Has the operator maintained documentation demonstrating that pipe removed due to external corrosion has been repaired or replaced with pipe that was coated and cathodically protected?	Not Applicable
General Comment:	<u> </u>	
No piping was removed due to external corrosion in the Ja	cksonville Service Area in 2013-2014.	
TRAINING - 83 IL ADM. CODE 520		
<u>Category Comment:</u> Training documentation was not reviewed during this audit located in Pawnee, Illinois.	t. It is reviewed during the Operator Qualification audit performed at the Amerer	n Illinois Training Center
[520.10(a) (1)]	Has the operator maintained documentation demonstrating that personnel have received adequate training?	Not Checked
[520.10(a) (2)]	Do training records include verbal instruction and/or on the job training for each job classification?	Not Checked
[520.10(b)]	Has the municipal operator maintained documentation demonstrating that personnel have received adequate training?	Not Checked
[520.10(a)(5)]	Are procedures periodically updated to include new materials, new methods of operation and installation, and changes in general procedures?	Not Checked